

CEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-27164

CUSTOMER ORDER NO.

ATTN ED JOY

119362

RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

107/92

12/11/92

DK 9-90

R6886666

700 243

FS

SERIES

W/STUDS

SCOPE BASE

L/SIGHTS

SHIP TO:

DENNIS HARDWARE
1 GRAVOIS RD
FENTON

MO 63026

DENNIS HARDWARE
1 GRAVOIS RD
FENTON

MO
63026

CUST NO:003106 ILION

UNIT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

CONDITION

EW

IGHTLY WORN

JORN

ERY WORN

INREPAIRABLE

IARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

TOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

E

A1

B1

GER GROUP

ASSY.

REL ASSY.

ASSY.

ID

AL

FAULT

Unable to duplicate customer concern.
Disassembly revealed trigger assembly adjusted instead of firing
switch found on trigger housing from removing adjustment screw
replaced. Trigger Pull 3 1/2 lbs

S

See left - D1

COMMENTS

Replaced trigger assembly complete
at 1/2 normal replacement cost, as
portion of good unit

Clear photos

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

122

GALLERY TESTER

DATE

DATE

DATE

DATE

OFFICE COPY

RD6L