

gunsmith and coming to Austin in 1981.

He informed me that yes he had run into this problem on Remingtons before.

Sirs - to say the least, you are fortunate someone did not get wounded or killed from the malfunction of this gun. You would have had one hell of a lawsuit on your hands. (I hunt with my two sons)

The gunsmith at Whitetail informed me that the bolt mechanism was fitting and full of factory gunk and that the trigger setting was not even near factory specifications. He asked me how long I'd had the gun and how old it was. Like I've said here - This is my 3rd season to use the gun. I purchased it brand new. I take care of my hunting and fishing equipment like a woman does her silverware.

I personally think that Remington Fike Arms Co. should pay for the incurred repairs to this rifle and thank God like I do, that no one was injured or killed.

The cost to me (their bill) is for 29.56. (Copy inclosed) If you want to write Whitetail Gun Sale & Service their address is:

110 North IH 35, Suite 170, Round Rock, Texas, 78681
(512) 255-0154. I am sure they will be happy to send you a copy of the free work order & work done on the bolt action and trigger, safety mechanism.

I expect a reply from your company, very soon.

I thank you,
ALVIN L. EPPERSON, JR.
(Home address) 9523 Quail Village Ln.
Austin, TX 78758