


Since we found the trigger assembly to be outside our specifications, we can either readjust the present assembly or, if it will better restore confidence in the rifle, we will install a new trigger assembly at no-charge as a good-will gesture (either option subject to a \$10.00 handling and return shipping fee). We will await the decision and reply.

Thank you for affording us the opportunity to examine the rifle and report our findings.

Sincerely,

A handwritten signature in cursive script that reads "J.A. Stekl" with "tpp" written below it.

J.A. Stekl, Specialist
Product Service

JAS:tpp