

RECEIVING AND ESTIMATING REPORT

REPRINT CUST NO: 047129 C.O.D

COMMENTS

INITIAL

CUSTOMER ORDER NO.

PS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

MODEL AND GRADE

ORDER

97/31/91

08/07/91

AA 3-80

A3206742

700 30-06

ADL

R 91-15196

ACCESSORIES

W/STUDS

FROM:

GUNNS GUN & PAWN
PO BOX 1657
7388 HWY 21 N
KEYSTONE HGTS
USA

FL 32656

SHIP TO:

GUNNS GUN & PAWN
PO BOX 1657
7388 HWY 21 N
KEYSTONE HGTS
USA

FL 32656

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

8-29-91

UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐ NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

CUSTOMER'S REQUEST

Hammer falls when loading, very dangerous.

MAIN FAULT

As received, trigger assembly and bolt stop inoperative. Trigger assembly is contaminated with gummy residue - internal piston sticking to side plates - rifle would not cock.

ARTS

Send estimate to clean rifle and trigger assembly, if possible. If not possible, send quotation for new trigger assembly.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6923 REV. 7/90

PPS 02081