

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER R92-17864	
INITIAL FPS		CUSTOMER ORDER NO.		ATTN: JIM STEKL			
DATE RECEIVED 08/24/92	DATE OPENED 09/02/92	DATE CODE CZ 4-75	SERIAL NUMBER 6855517	NEW SERIAL NUMBER	MODEL AND GRADE 700 270 WIN BDL		
ACCESSORIES		SLING STRAP W/STUDS		W/SWIVELS		SCOPE BASE	
FROM:				SHIP TO:			
MAIL BOXES ETC. ROBERT HUMASON 5114 BALCONES WOODS DR. AUSTIN TX 78759				MAIL BOXES ETC. ROBERT HUMASON 5114 BALCONES WOODS DR. AUSTIN TX 78759			
CUST NO: 065806 C.O.D							
ACCOUNT NUMBER		ACCOUNT NUMBER W/C		PROM. DATE		ESTIMATED VIA	
				WRITE ☐ CLEAN/TEST		UPS	
GUN CONDITION				REPAIR CHARGE			
☒ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED				EXCISE TAX INSURANCE UPS PARCEL POST TOTAL			
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT	
CYCLE	A1	B1					
TRIGGER GROUP		B2			E1	E1 and E2	
BOLT ASSY.		B3			E2	F2	
BARREL ASSY.		B4		D1	E3	F3	
REC. ASSY.		B5		D2	E4	F4	
WOOD				D3	E5	F5	
METAL							
MAIN FAULT: <i>Could not duplicate complaint. Rifle and trigger are operated normally. Inspection of the trigger assembly did reveal very excessive movement of oil, dust, etc. but this condition did not adversely affect operation of the assembly. Trigger pull 5 pounds; over lift .008"</i>							
PARTS				COMMENTS			
				<i>Per phone call to customer, install new trigger assembly at normal cost, as gesture of good-will.</i>			
				<i>New style - no bolt lock</i>			
				<i>Customer does not want return C.O.D</i>			
				<i>send bill</i>			
REPAIRMAN		PROOF		CLEAN	TEST	TARGET	PATTE
GALLERY TESTER		DATE		DATE	DATE	DATE	DATE

OFFICE COPY