

# RECEIVING AND ESTIMATING REPORT

INITIAL <b>IJM</b>		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED <b>1/27/90</b>	DATE OPENED <b>11/30/90</b>	DATE CODE <b>CO 4-77</b>	SERIAL NUMBER <b>A6598848</b>	MODEL AND GRADE <b>700 243 BDL</b>		ORDER <b>R 90-3110</b>	
ACCESSORIES <b>W/STUDS</b>							

FROM: <b>IRWIN, KEITH C RR 3 HMHP LOT 14 ALBIA IA 52531</b>		SHIP TO: <b>IRWIN, KEITH C RR 3 HMHP LOT 14 ALBIA IA 52531</b>	
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/> CLEAN/TEST	VIA <b>UPS</b>

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

SUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: *The rifle fires when the bolt is closed.*

MAIN FAULT: *None found - cannot duplicate complaint. Trigger assembly and safety operate properly. Trigger pull 4 1/2 pounds; cam-lift .008. Trigger assembly is contaminated with dirt & partially dried oil, however, and in cold condition could possibly cause a problem.*

ARTS  <i>P.L. set up file - attached copy to Hutton</i>	<i>Offer to clean present assembly, if possible. Or we can replace trigger assembly at <del>customer's expense</del> is minimal charge, if it will better restore confidence in the shop, as a gesture of good-will.</i>				
	REPAIRMAN <b>JOB</b>	PROOF	CLEAN	TEST	TARGET
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90