

COMMENTS

ORDER
R 94-11762

FROM:

SHIP TO:

KITSCH, KENNETH
115 SHARON DRIVE
DOUGLASSVILLE

PA 19518

KITSCH, KENNETH
115 SHARON DRIVE
DOUGLASSVILLE

FA
19518

CUST NO: 095304 C.A.D.L

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Mar 11-76. Shot has been glass belted and trigger adjusting screws have been altered outside of factory. Trigger operates correctly as received. Repairs trigger assembly strictly as a gesture of good will to restore customer confidence in rifle.

[illegible]

OFFICE COPY

RD6925 REV. 1/84

PPS 02754