

John D. McKay

-2-


July 11, 1986

is a mechanical malfunction having to do with the trigger and sear relationship. If your rifle is evidencing a fire when safety is released malfunction, please send the rifle to our firearms plant in Ilion, New York for examination. We will make a thorough inspection and will send you a written report on our findings prior to undertaking any further action.

If this arrangement is acceptable, please send the rifle via UPS, transportation Collect to Remington Arms Company, Inc., 14 Hoeffler Avenue, Ilion, New York 13357, Attention: E. F. Sienkiewicz.

Thank you for calling this matter to our attention.

Very truly yours,


Robert B. Sperling
Counsel

RBS:aw

PPS 03350