

RECEIVING AND ESTIMATING REPORT

INMER ORDER NO.		COMMENTS	
		MOUNTAIN RIFLE	
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER
2/26/88	03/03/88	WH 8-87	B6880822
MODEL AND GRADE		ORDER	
700 270 MT		R 88-07363	
SCOPE MNTS		SCOPE BASE	

SHIP TO:	
CARL MCKENZIE 429 LONGWOOD TR. MADISON MISS.	CARL MCKENZIE 429 LONGWOOD TR. MADISON MISS.
39110	39110

NT NUMBER	FROM DATE	ESTIMATED	VIA
			UPS
CHARGE	TAX ST	INSURANCE	UPS
	TAX CITY		
		PARCEL POST	TOTAL
			\$

CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ QUOTE

MEASUREMENTS
re-attached description of incident → Fired when safety moved from FIRE to SAFE position - Damaged truck door

FAULT	DEMERIT CODE

1-19-88
EFS/RKP
Reassemble gun with original trigger which is perfect. DO NOT install this gun. ASAP to about customer RHP
THRP ship prepaid BLUE Jerry B. to handle - 3-3-88 RHP
* COLD THE CONNECTOR - check for follow down:
① Try to duplicate incident from Fire to safe + then from safe to fire
② Do this without ammo +, if thought proper, with ammo in gallery.
ATTENTION: ABOVE SERIAL NUMBER IS ON ***** THE "TARP" MASTER FILE

Note Return
Custom Scope
Rings in Box
③ Do any other non destructive test you think proper to try to duplicate incident.
④ Check connector condition
⑤ Give findings to KD Green x 407 ASAP.

COMPUTER REF. ONLY	PROOF
	(CLEAN) (TEST) (TARGET)
	REPAIRMAN

OFFICE COPY