

Problem: Fires when chambering
bullet or when safety is
activated.

Harold Palmour

HAROLD H. PALMOUR
4565 FM 3126
LIVINGSTON, TX 77351
(409) 566-4033 OR (409) 967-8885
MOBILE (409) 327-0861

Co. Inc.
e Dept.

e.

5557

Atten: Dennis Sanita