

bcc: D.J. Sanita
R#03644
clean trigger assembly & gallery test

February 8, 1985


-2-

We are, as a gesture of good-will, forwarding the rifle to our Arms Service Division for thorough cleaning and re-testing at no-charge to you, in the hopes that your faith in the rifle will be restored, as the incident you experienced was caused by conditions beyond our control.

We strongly recommend, that in the future, any work performed on the rifle should be done by a Remington Recommended Gunsmith. We are enclosing a list of our Warranty Repair Stations for possible future reference.

Thank you for allowing us the opportunity to examine your rifle and report our findings.

Sincerely,


J.A. Stekl, Supervisor
Product Service

JAS:tp
encl.

PPS 03786