

RECEIVING AND ESTIMATING REPORT ✓

INITIAL		CUSTOMER ORDER NO.		COMMENTS			
LCS							
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER		
08/22/90	08/29/90	DD 9-83	7624325	7 243	R	90-2	
ACCESSORIES		W/STUDS					

FROM:

SITTON, TOMMY C
RT 2 BOX 325-B
HORSE SHOE NC 28742

SHIP TO:

SITTON, TOMMY C
RT 2 BOX 325-B
HORSE SHOE NC
28742

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	PROM. DATE	ESTIMATED	VIA
					UPS

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

Rifle fired upon closing bolt with "safety on"

MAIN FAULT

Cannot duplicate complaint - Trigger and safety commonly operate properly - Trigger pull 4 1/2 lbs, over-leaf .014"
This rifle cannot fire with safety on, because firing pin is stuck

PARTS

We are prepared to return gun as received or, if it will better restore confidence in rifle, offer to install new trigger assembly at 1/2 normal charge. Rifle is 7 years old

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV