

RECEIVED

NOV 22 1983

J. A. STEKL

O.S.
#1230

5530 Parkhill Court
Baton Rouge, La. 70816
Nov. 16, 1983

Remington Arms Company, Inc.
Arms Service Division
Ilion, New York 13357

Dear Sir,

I recently purchased a Remington Model 700 BDL rifle in a 25-06 caliber. The serial number is B6425005. I am very disappointed that the bolt lock type safety is no longer used on this rifle. My style of hunting requires this type of safety.

I have several Model 700 rifles and it appears that the bolt lock safety switch on the older rifles will inter-change with the newer type safety switch. If this is true, I would like to purchase the bolt lock type safety switch for my new Remington 25-06 Rifle.

You can either bill me for the switch or mail it COD.

Very truly yours,


Max O. Usrey 111

