

Greg Woodson
Rt. 5 Box 189
Gatesville, Texas 76528
817-865-7061

Tron
Handwritten signature
Rogers

RECEIVED
NOV - 4 1985
K. D. GREEN

Remington Arms Company, Inc.
Dept. CB
939 Barnum Avenue
Bridgeport, Conn. 06602

October 22, 1985

Dear Sir,

I purchased a 7mm Remington Magnum Bolt Action Rifle on 11-6-81. The model number is 700, grade ADL with a 24 inch barrel length, order #5776.

I have fired this rifle no more than a dozen times, and have kept the rifle cleaned at all times.

Last year on the first day of deer season, I loaded two rounds into the chamber. I saw no deer that day, so I attempted to unload the two rounds at which time complications occurred. I pulled the bolt back to kick the round out and the gun fired, causing considerable damage to my pickup. I then closed the chamber and repeated all of the same actions. Once again the gun fired. I examined the chamber and noticed fragments of brass throughout the chamber.

Needless to say, I have not used the rifle since that incidence.

Please guide me to the proper procedure to repair my gun. Because of personal feelings I have toward the store where I purchased the gun, I do not choose to return it there, so please offer me another alternative.

Please find enclosed a copy of my receipts. If any additional information is needed please feel free to contact me.

As you are aware, deer season is fast approaching, therefore I am anxiously awaiting your reply.

Thank you for your prompt attention to this matter.

Sincerely, *Greg Woodson*

Greg Woodson

CC: File

RECEIVED
OCT 29 1985
CONSUMER SERVICE

PPS 05587