

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-35295

INITIAL
FPS

CUSTOMER ORDER NO.

ATTN: DENNIS SANITA

*(5th Floor at Gypsum)*DATE RECEIVED
12/05/94DATE OPENED
12/08/94DATE CODE
DWW 9-50SERIAL NUMBER
121428

NEW SERIAL NUMBER

MODEL AND GRADE
721 - 270 WIN

ACCESSORIES

L/REAR SIGHT, STUDS

FROM:

AMERICASE
ATTN: STEVE
1610 EAST MAIN
WARAHACHIE

TX 75165

SHIP TO:

AMERICASE
ATTN: STEVE
1610 EAST MAIN
WARAHACHIE

TX

75165

CUST NO: 071899 C.O.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059015

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

*Left pop 1950, upon receipt we could not duplicate the reported
Concern. However, the trigger was working properly. Manufacturer advised that
the action & trigger assembly we bought with a strong suspicion. The bolt stop
is now now seized up. The contact in the trigger adjustment screw has been
snapped off, indicating they have been tampered with a good time. Subsequent
found inside the trigger housing. The state is checked then the pop was
adjusted to be correct. Shipping container was not returned to the
UPS inspector.*

PARTS

COMMENTS

*Repaired the broken trigger assembly &
clean action at N/C*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

*Custom Shop with supply state
correctly*

OFFICE COPY

RD6925 REV. 1/94

PS00569