


Serial Number: **6352608**

Model: **700** —



RE00074147

UPS DRIVER INSTRUCTIONS: YOU ARE AUTHORIZED TO ACCEPT THIS PACKAGE WITHOUT A PICKUP RECORD.

Name: **Bill RANTON**

Company:

Street: **10016 FERNHAVEN CT**

City: **DEVIS**

State: **OH**

Zip Code: **450251**

REF #:

TO: **DENNIS SANITA**
REMINGTON ARMS
14 HOEFLER AVE
ILION NY 13357

A.R.S.



UPS 3 Day SelectSM

3

TRACKING NUMBER



1Z E13 390 57 5000 1125

UPS Authorized Return ServiceSM

01118613

1/95 W

12/18/03

*Oct 10
OT
1/10*

*You may we could not duplicate
the reported concern -*

Bolt stop release broken

*Tug Wilson Components working slugs with from being
mixed with other materials. Per maintenance*

PS00709

Attention:

Dennis T Sanita

This rifle will shoot when bolt is manually locked down. I didn't have a shell in the rifle at time but 'cocked' indicator rear bolt was going forward as cycling over,

Scope rings removed
Butt plate recoil
pad removed.

Thanks

Wayne Tolson
CPO ASW/R