

DWIGHT E. BOWLER
813 CHARLES
YPSILANTI, MI.
48198

This rifle was fired
and when I loaded the
second round and locked
the bolt, the gun went off.
Now, at times, when I
load the second round
it will not cock the
bolt. We petition for an Elk permit
for Sept. We would like to be able to
use this gun.

Thank You

Dwight E. Bowler
313-487-7075