

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product Service.

ORDER
R 93-11334INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED

05/05/93

DATE OPENED

05/06/93

DATE CODE

PR 6-68

SERIAL NUMBER

352274

NEW SERIAL NUMBER

MODEL AND GRADE

700 308

ACCESSORIES

W/STUDS

SCOPE BASE

HARD CASE

L/REAR SIGHT

FROM:

COLLINS, HERB
411 MARYLAND
MALAKOFF

TX 75148

SHIP TO:

COLLINS, HERB
411 MARYLAND
MALAKOFF

HERB COLLINS
ADL
CBSE
RT 4
Athens, Tex 7
75148
ATTN: Shipper

CUST NO: 078869 C.O.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

20.00
5.00
25.00

Via UPS
COD

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP	"	B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B5			E3	F3
REC. ASSY.				D1 D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT Unable to duplicate customer concern. Examination did reveal the action, trigger assembly, and bolt stop were bound and sticky. Gummy substance. Bolt stop release would not reset.

PARTS

COMMENTS

Trigger Pull - 6 lbs.
Gun Left - .085

Repair trigger assembly complete and clean action at 1/2 normal up replacement cost no question of good. Go ahead per phone 6/4/93

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD8925 REV. 1/9