

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-27671INITIAL
J.M.

CUSTOMER ORDER NO.

DATE RECEIVED 12/08/93	DATE OPENED 12/16/93	DATE CODE RTT 1-48	SERIAL NUMBER 24517	NEW SERIAL NUMBER	MODEL AND GRADE 721 30-06
---------------------------	-------------------------	-----------------------	------------------------	-------------------	------------------------------

ACCESSORIES

L/REAR SIGHT STUDS

FROM:

SHIP TO:

Steph
CEILO GUNWORKS
316 WEST 4TH STREET
THE DALLAS

CEILO GUNWORKS
316 WEST 4TH STREET
THE DALLAS

OR

97058

CIS N:068321 C.O.D.L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	-------	------------	-----------	------------

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☒ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
RIGGER GROUP		B2			E1	F1
OLT ASSY.		B3			E2	F2
ARREL ASSY.		B4		D1	E3	F3
EC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Chamber is ext. max. left 1/4 1948

Unable to duplicate firing on Ball Charge. However, observation indicated that a 3 trigger and ejection issues have been the subject of previous, indicating they have been beyond repair.

TS COMMENTS

*This? returned to repair on
upholster per Customer Order*

REPAIRMAN F.B.	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS01367