9861 Dyer Street, No. 7 • El Paso, Texas 79924 • (915) 755-7845

19 May 1993

Remington Arms Co. Arms Service Division 14 Hoefler Ave Ilion, NY 13557

re: Remington 700 BDL repair

Dear Sirs:

I am returning a Remington 700 BDL serial number A6252874, caliber 22-250 for repair. The rifle discharges when the safety is disengaged. I talked to your service department on 18 May and made arrangements to return the rifle.

Your cooperation in this matter is appreciated. If I can be of any assistance please feel free to call. I have enclosed a copy of my FFL for your convenience. Thank you.

Sincerely,

Dale N. Richardson

Owner