

February 25, 1999
Mr. Paul G. Dunn
RR 3 Box 46A1
Montrose, Pa. 18801
(717) 278-4184

Remington Arms Services
Consumer Products
14 Hoesler Avenue
Ilion, New York 13357


To Whom it may concern:

I am enclosing the bolt assembly from my model 660 serial # 129647, for your inspection, and to be repaired or replaced as needed.

On two occasions this weapon discharged accidentally, once while loading, and once when unloading causing my concern that the bolt was at fault.

I hope you will be able to identify the problem and correct it.

Yours Truly,


Paul G. Dunn