


December 14, 1993

Set up full 94
DENNIS SAWYER



Near Remington Arms,

I have had a BDL Remington, 25.06 gun that I bought from you back in the mid.- 70's. It is scoped with a 3x9 Leopold of the same year.

This has always been my "old Faithful" whitetail/mule deer gun, it has put many deer on the ground. It has always been reliable.

But, this year I crawled across a fence about 12 miles South of Pagosa Springs Colorado. After crossing the fence and getting situated I loaded my rifle and when I closed the bolt, it decapitated a small pine tree above me. After settling down from the unexpected shoot and the color came back, I unloaded the clip. I dry fired it about 8 or 10 times by closing the bolt, not even touching the trigger. If you opened the bolt and put it on safety it wouldn't discharge as you closed the bolt.

After the 8 or 10 dry fires it quit doing it and resumed normal operation and has worked fine everytime since. But, you know I will never be able to trust that gun again. Is there anything that can be done to insure that this problem will not reoccur? Please Respond.

Thanks

A Lifetime Remington Shooter

Bertell Blockery

Bertell Blockery
Rt. 3 Box 746
Groesbeck, Texas
76642

Phone: 817-729-5253

1/3/94 Called Customer - he agreed to return Call they issued 1/3/94

Bertell Dockery, Manager
Old Fort Parker State Historical Park
Route 3, Box 746
Groesbeck, Texas 76642



Paul Heath



Remington Arms Company Inc.

Wilmington, Delaware

19898 RECEIVED

DEC 20 1993