

RECEIVING AND ESTIMATING REPORT				COMMENTS		ORDER	
INITIAL JJM	CUSTOMER ORDER NO.					R 94-33145	
DATE RECEIVED 11/16/94	DATE OPENED 11/17/94	DATE CODE AT 3-70	SERIAL NUMBER 6307539	NEW SERIAL NUMBER	MODEL AND GRADE 700 243	BDL	
ACCESSORIES W/STUDS			SCOPE BASE				
FROM:				SHIP TO:			
ELSNER, AL 4516 CRIMSON LEAF DR LAS VEGAS NV 89130				ELSNER, AL 4516 CRIMSON LEAF DR LAS VEGAS NV 89130			
L				CUST NO: 108405 C.O.D.L			
ACCOUNT NUMBER 063123		ACCOUNT NUMBER N/C		WRITE ☐	FROM DATE 11-29-94	ESTIMATED 11-29-94	VIA UPS
GUN CONDITION				REPAIR CHARGE 20.00			
☐ NEW ☒ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED				EXCISE TAX INSURANCE UPS 8.00 PARCEL POST TOTAL 28.00			
CUSTOMER CONCERN		AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1					
TRIGGER GROUP		B2			E1	F1	
BOLT ASSY.		B3			E2	F2	
BARREL ASSY.		B4			E3	F3	
REC. ASSY.		B5			E4	F4	
WOOD		C1			E5	F5	
METAL		C2					
MAIN FAULT: <i>Left mag 1970, upon receipt we could not duplicate this condition. Examination did reveal that the trigger adjustment and stop were both set to -1. The trigger is not engaged, and the trigger part manual before was 2. Trigger part - 2 1/2 in.</i>							
PARTS				COMMENTS			
#26345				<i>Set the trigger stop to 1/2 the normal again not in a quarter of good will. Go ahead</i>			
REMARKS RTB				PROOF	CLEAN	TEST	TARGET
GALLERY TESTER				DATE	DATE	DATE	DATE

OFFICE COPY

FD3025 REV. 1/84