

Serial
Number:

E6717397

Model: 700



RE00047183

5/24/02

Ref fuel on ref release

Action (hand bracket) & trigger arm
Components rusty - appear ref was exposed
to excessive moisture & not properly cleaned

Refuel trigger arm & clean action at no charge
as part of Goodwill - normally this condition
would warrant a repair charge

Charge 230145