

## RECEIVING AND ESTIMATING REPORT

COMMENTS

Product  
Service

ORDER

R 94-28955

INITIAL  
JJM

CUSTOMER ORDER NO.

W/FLOOR PLATE, MAG BOX, MAG SPG, FOLLOWER, SCREWS

DATE RECEIVED  
10/10/94DATE OPENED  
10/11/94DATE CODE  
RS 11-69SERIAL NUMBER  
6289676

NEW SERIAL NUMBER

MODEL AND GRADE  
700 30-06

ACCESSORIES

L/WOOD

L/SIGHTS

FROM:

GINSKI, JOSEPH  
1115 S CLINTON ST  
BALTIMORE

MD 21224

SHIP TO:

GINSKI, JOSEPH  
1115 S CLINTON ST  
BALTIMOREMD  
21224

CUST NO: 105374 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW  
☒ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE  
☐ MARRED

REPAIR CHARGE

20.00

EXCISE

TAX

INSURANCE

UPS

8.00

PARCEL POST

TOTAL

28.00

| CUSTOMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|------------------|------|----------|--------|----------|-----|---------|
| CYCLE            | A1   | B1       |        |          |     |         |
| TRIGGER GROUP    |      | B1       |        |          | E1  | F1      |
| BOLT ASSY.       |      | B3       |        |          | E2  | F2      |
| BARREL ASSY.     |      | B4       |        | D1       | E3  | F3      |
| REC. ASSY.       |      | B5       |        | D2       | E4  | F4      |
| WOOD             |      |          | C1     | D3       | E5  | F5      |
| METAL            |      |          | C2     |          |     |         |

MAIN FAULT

Upon receipt, rifle would follow down when closing the bolt.

Inspection revealed that all 3 trigger adjustment screws have been tampered with (w - set). Adjustment in out of sequence. Trigger housing is marked as

PARTS

# 26345

COMMENTS

Replace the complete trigger assembly & clean action at 1/2 normal replacement cost, as a gesture of good will. Go ahead

REPAIRMAN

REP

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS02897