

Remington Arms Co., Inc.
14 Hoefler Ave.
Ilion, NY 13357

Warren E. Howe
1804 W. Church Rd.
Star Prairie, WI 54026

Dear Sir;

I read an article in Field and Stream about upgrading the safety on the Model 700. I have the older style that does not allow me to open the bolt without taking the safety off, and would like you to upgrade my safety. I have experienced two accidental discharges with this rifle, while opening the bolt. Please go over it and fix whatever is wrong. (Ser. No.: A6459623)

Charge my credit card for any parts and services charges.

Visa
4800 1250 4605 2980
Expires 08/05

Please ship my rifle to me at:

Warren E. Howe
% Hudson Machine & Tool
1750 Ridgeway St.
Hammond, WI 54015

Thank you.

Warren E. Howe

Warren E. Howe

*Very Clean TA
Safety detent not
working - install new
TA, clean action \$20
under bolt lock modification
program - Credit card
info provided.*

FLS 1/10/03

Serial
Number:

A6459623

Model: **700**



RE00058977