



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00065982	Description/Serial Number 36221	Repairman - Richard Hilts Date Received - 6/3/2003
Account # - R-	Model 700 Center Fire Caliber: 7 MM ADL	Estimate Date - Current Date - 6/9/2003
Customer JOSEPH HANZL 8 DOGWOOD LANE PUTNAM VALLEY, NY 10579 US	Return To JOSEPH HANZL 8 DOGWOOD LANE PUTNAM VALLEY, NY 10579 US	
Phone (H) (845)-528-5876 Phone (W)	Fax Email	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M240	BOLT LOCK SAFETY MODIFICATION	M240	BOLT LOCK SAFETY MODIFICATION
M992	GUN DISCHARGED WHILE UNLOADING	M992	GUN DISCHARGED WHILE UNLOAD

Material #		MaterialDesc		Repair			
				Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part							
F26345		700 TRIG ASSB RH		1	1	0	Y
Part Total:				1	1	0	
Service							
4000104		ARMS SERV SHIPPING & HANDLING		0	0	0	Y
4000116		GR-LABOR		20	20	0	N
4000118		GR-CLEAN		1	1	0	Y
4000119		GR-TEST		1	1	0	Y
Service Total:				22	22	0	

ProblemNotes		bolt lock modification install new trigger clean action FLS6/3/03			
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date