

3/22/94
Rem Arms Co Inc Remailed 4/6/94
Ilion N.Y.

Dear Quality Control Re 700 Rifle

Based on "60 Minutes" report on 3/20/94
I suspect I (may) own a Remington
Bolt action 700 series rifle that is
subject to "kicking" or accidental?
Discharge (firing without using the trigger).


I understand @ 1% of all 1975 and
prior Remington rifles are subject to
malfunction... I experienced such a
malfunction (I think) in the early 1970's
when rifle fired through the wall of the
house when bolt was closed.

I have a Remington 700 series bolt
action rifle (308 WIN) # 234770
PAT NO 2,473,373, 2,514,981 purchased
sometime in the early 1970's.


Please research and advise me if
the rifle is one that is subject to mal-
function and if so what is the next
step. Thanks

C-File

Sincerely
J. Halton



L Hg Lwca Jr
RD 2
Bristol, VT



Remington Arms Company
Ilion, New York