

Remington

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700 ADL 270		Serial Number: 6893716	
Name: ROBERT HAYDEN		Date of Purchase: 8/2/04	
Address (no PO Boxes): 578 WHITE OAK GROVE ROAD NE			
City: RIVER		State: VA	Zip: 24149
Phone (Daytime): 540 763-2400		Fax:	
E-mail Address:			
Please describe your problem: RIFLE HAS DISCHARGED (3) Times when CLOSING BOLT.			
77654			
Additional Information: (Ammo type, brand, handload specifications, etc.)			
FEDERAL Premium 130GR SPIRE POINT.			
NOTE: Prior to shipping your firearm, contact the Repair Center for services			

Serial Number:

6893716

Model: 700



RE00077654

IF FIREARM OR IN THE SAME BOX WITH THE FIREARM.
DO NOT SEND SPENT SHELLS PLEASE SEND THEM IN A
CODE), TELEPHONE AND MODEL AND SERIAL

in shipping and handling. Preferably,
insured.)
or damage.
Remington is not responsible for
loss of insurance from your carrier.

TP 4/2/04

Date Recd

EZ

10/25

2/27/04 Action & trigger assembly covered with sticky substance
& rust Per maintenance
Repair tag amount \$20.00

P. Adams

B.M. Program

2/3/2004

<http://www.remington.com/support/repairsvc/repairform.htm>