

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-20104INITIAL
FPS

CUSTOMER ORDER NO.

Product Service

DATE RECEIVED
06/29/94DATE OPENED
06/30/94DATE CODE
CR 4-68SERIAL NUMBER
344159

NEW SERIAL NUMBER

MODEL AND GRADE
700 270 WIN

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

K & K TRUE VALUE HDWE
1818 GRANT ST
BETTENDORF

-IA 52722

SHIP TO:

K & K TRUE VALUE HDWE
1818 GRANT ST
BETTENDORFIA
52722

CUST NO: 010083 ILION L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA
UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE 20.00

EXCISE

TAX

INSURANCE

UPS 8.00

PARCEL POST

TOTAL 28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt, we were unable to reproduce the customer concern. However, disassembly revealed that the trigger adjustment and stop screws have been re-set. The action and trigger housing are dirty and gummed up with a sticky substance. The bolt stop screw will not rotate.

PARTS

COMMENTS

1468 Trig. Part - 4.00
Gun oil - .009

Repair the complete trigger assembly and clean the action at 1/2 normal replacement cost, as a gesture of good will.
JP Hance

26345

REPAIRMAN TAL	PROOF	CLEAN ☒	TEST ☒	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD8925 REV. 1/84