

IVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 77-25671

CUSTOMER ORDER NO.

ATTN: D J SANITA

IVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
9/93	12/01/93	EJ 10-89	C6462090		700 270 ADL
IES	W/STUDS	SCOPE BASE			

SHIP TO:

LESTER, CHARLES
120 JUANITA AVE
WILLS POINT

TX 75169

LESTER, CHARLES
120 JUANITA AVE
WILLS POINT

TX
75169

CUST NO: 087882 C.O.F.

NUMBER	ACCOUNT NUMBER N/C 059015	WRITE ☐	PROM. DATE	ESTIMATED	VIA
DITION					5631197859
LY WORN	UP5 2nd day Cui				REPAIR CHARGE
WORN					EXCISE
PAIRABLE					TAX
ED					INSURANCE
					UPS
					PARCEL POST
					TOTAL

ER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
GROUP	B1					
SY.	B2					
ASSY.	B3					
Y.	B5					
	B2					
	B2					

Want ship by 12/5/93

The rifle discharged under 1 shot the shot

New rifle, only shot to time

Wanted to duplicate customer concern. Rifle function as designed.

Trigger pull - 5 1/2 lbs

Spring lift - .015

Ammunition did reveal that the shot is cracked at the magazine well

COMMENTS

Replace component trigger screw & shot screw. no further of good work to help next shot in rifle

Ship back in rifle hand case

Go ahead per phone 12/1/93 with Mr. Lester

To A/S 12/2/93

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE