

36514

11-20-01

This gun has never been fired, and I am very disappointed after waiting for seven months and ten days to pick it up from the gun shop, where I purchase it, this is what happen, when I took it home, remove it from the box, with the safety mechanism in the fire position I slide the bolt handle forward then push the bolt handle down to lock it, making sure everything was working ok, with out touching the trigger the bolt mechanism went into firing mode, what a horrible shocking surprised, I am very fortunate there was not any live cartridges in the chamber, on three separate occasion this has happen, when I try to install the bolt assembly, I know Remington has a very good reputation, but this incident is very scary, if possible I can get a refund it would be great, if not please make sure the firearm is safe to use.

Thank you

*Anthony Marciano*  
Anthony Marciano

PS to  
Reimburse  
\$805.00

**MODEL 700 VARMINT SYNTHETIC LH**  
**ORDER NO. 27549**  
**SERIAL NO. E6619475**  
**PROOF OF PURCHASE NO. 47700275499**

Repair this gun for  
w/p sales -  
close R&E  
FLS 11/30/01