

File Number:	11120	Arms Service number:	9901007
Last Name:	NORWOOD	First Name:	VICTOR
Street:	464 SCIOTO ROAD	City:	UNION
State:	TN	Zip:	37692
Home Ph:		Home Ph:	423-743-8894
Work Ph:		Product Type:	F A T O
Type Concern:	S	PL PD P S C	Concern Code:
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4040	Cause:	OTHER - STICKY RESIDUE
Assigned To:	SUPRY	Classification:	UNION UNO 3
Settlement Details:	REPLACE FC NIC	Settlement Amount:	\$35.00
Date Opened Rem:	01/12/1996	Date Opened by PIS:	01/13/1999
Date of Incident:		Date Closed:	01/13/1999
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	B6809916
RAMAC:	700	Litigation:	
Cusofity:		PreLitigation:	
Comments:		Could not duplicate customer concern - Sticky residue found inside the assembly - Replace FC nic as gesture of goodwill	
Type of Modification:	8:55:48 AM	Date of Modification:	01/13/1999