

NORTHWESTERN INDUSTRIES
416 West Main
SIOUX FALLS, NORTH DAKOTA 58072

(701) 845-1031

Remington arms

Memo

LETTER

Date 4/6/93

Subject 700 BDL 2-6-50
SIN 6501534

Dear Sirs:

The enclosed rifle fires on closing at times,
please repair or replace.

Sincerely,

Leon Pytlík

LEON PYTLIK

☐ Please reply

☐ No reply necessary

SIGNED

COMMENTS

was that all 3 trigger adjustment screws
were compressed with return the factory. No return on adjustment
screws, will return from our department now.

Revised trigger assembly complete
and then return it to owner
replacement cost at price of \$200
will.

REPAIRMAN

J103

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

PS04567