

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700
Madison, NC 27025-0700

Parts/Repairs 800-243-9700
Fax 336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00044029	Description/Serial Number C6398076 REPLACEMENT S7646812	Date Received - 3/26/2002
Account # - R-	Model 700 Center Fire Caliber: 300 WBY	Estimate Date -
	BDL W/ SYN BELL & CARLSON STK.	Current Date - 8/28/2002
Customer MCCAULEY WEBSTER & EMRICK ATTN JAMES MCCAULEY/AL POLING 1710 WASHINGTON BLVD BELPRE, OH 45714 US	Return To MCCAULEY WEBSTER & EMRICK ATTN JAMES MCCAULEY/AL POLING 1710 WASHINGTON BLVD BELPRE, OH 45714 US	
Phone (H) (740)-423-9548	Fax (740)-423-7705	
Phone (W)	Email jmccauley@1st.net	

Reported	Problems	Found
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123
		FORWARD TO PRODUCT SERVICE FOR

Problem/Notes	Technician's Comments
	Exchange this rifle for RAMAC 29561 M/Seven AWR 300 Rem S/A Ultra Mag (Custom Shop). Old rifle to be scrapped after exchange. FLS 7/30/02.

Serial Number: **S7646812**

Model: **700**



RE00052322

Material #	Material Description
Part	
29561	SEVEN AWR 300 REM SA U.MAG 22" CUS
Part Total:	
Service	
4000104	ARMS SERV SHIPPING & HANDLING
4000254	GR-FIREARM REPLACEMENT
Service Total:	

0	Y
1	Y
1	

Wrong gun supplied - Ramac 6047
with muzzle brake should be supplied
by custom shop. See Ron Emble he
has correct rifle - Put this gun back
in inventory.

FLS 9/17/02