

Dear sirs

The 600 Remington
has fired twice (separate
events) when the bolt
was closed on a live
cartridge. Other times
the safety would not go
off or when it was
off the trigger couldn't
be pulled. I called
Remington and they
said to send it in
it was on recall.

Please fix problem.

Set trigger pull at
2 to 3 lbs.