

RECEIVED

OCT - 5 1995

Remington Arms Co. Inc.  
Arms Service Division  
14 Hoefler Ave.  
Ilion, NY 13357

Subject: Safety failure on a 700 BDL 30-06

From: Winston C. Patton, II, 8209 Race Circle, Anchorage, AK'  
99504-4747

To Whom It May Concern:

On August 12, 1995, I was hunting black bear in Cooper Landing, AK. The previous day I had discharged the rifle one time. It was working properly.

The morning of the 12th, I shot a black bear. The bear was hit and immediately ran. I put a new round in the chamber as soon as I shot. When I tried to put the safety on, it would not come out of the fire position. I decided to chase the bear with the gun in the fire position. I located the bear, it was still moving, its' legs but was down. I was 10 feet away. I tried to shoot it again, but it would not fire, as if it were in the safety position. I tried to take it out of the fire position again but it would not come out. I was able to unload the gun. Once it was unloaded, it would go back into safety. I reloaded the gun at this time. The bear had since died - luckily for me. At this time I was just happy I had not been facing a wounded bear in this situation!


After I calmed down, I went back to my father-in-law's cabin. He met me outside. I was explaining what happened with the gun, I took the safety off and it discharged between us when I did this. FYI - I did not have my finger anywhere near the trigger - my father-in-law can attest to this!!!

In asking questions of many people, I found out that there is a history of these failures with your guns, have you corrected it? If you have, how do I get my gun repaired? A gunsmith told me you do not sell the parts to them.

Please respond ASAP - it is the middle of our hunting season now.

Concerned owner,

  
Winn Patton



PS04985