

RECEIVING AND ESTIMATING REPORT

CUST NO: 048532 C.O.D.			COMMENTS ATTN J STEKL W/WILLIAMS REAR SIGHT		
CUSTOMER ORDER NO.					
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
03/91	09/04/91	OR 7-68	118833	660 350REM MAG	R 91-17410
SERIES SCOPE BASE					

SHIP TO:		
STOKLEY, MIDGE P O BOX 792 (1 MILE HAINES HWY) HAINES USA	AK 99827	STOKLEY, MIDGE P O BOX 792 (1 MILE HAINES HWY) HAINES USA
		AK 99827

NT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
--------	-----	-----------	-----	-------------	-------

CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

USER'S REQUEST

"...iffy. Possible safety was released".

AULT: Cannot locate to complaint. Disassembly of rifle disclosed the following:
 1) Trigger assembly is defective, to be replaced per (231 page 6), as a
 result of "trigger" is in use but not positive. 2) Firing pin and spring are rusted
 and in trouble. 3) Trigger assembly is contaminated, the excessive lubrication
 is bad, it will with cold temperatures could cause a problem.

1) replace the trigger assembly per m/p 60
 2) Clean firing pin assembly

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE