

NO  
JERIAL  
#

Remington Arms Co.  
14 Hoefler Ave.  
Ilion, New York 13357

March 22, 1994

Gentlemen:

Last Sunday night, I was watching 60 Minutes on T.V. and they were talking about a problem Remington was having with the 700 series hunting rifles. They indicated that over the years, some of the rifles would fire upon closing the bolt or moving the safety from on to fire.

I own two Remington 700 BDLs, one is a 30.06 cal. and one is a 22-250 cal. and both have fired upon moving the safety from one position to another but not regularly.

Before someone gets hurt, please advise me what to do about this problem.

Bud



S. Stevens  
120 Judge Smith Dr.  
Marion, Arkansas 72364

501-739-3033

✓ 501-739-4621

