

JANUARY 26, 1994

REMINGTON ARMS COMPANY, INC.
ARMS SERVICE DIVISION
14 HOEFLER AVE.
ILION, NEW YORK 13357

DEAR SIR,

I PURCHASED THIS RIFLE IN THE LATE 1960's AND HAVE HAD SOME OF THE GREATEST HUNTING EXPERIENCES OF MY LIFE. IT'S BEEN A MAGNIFICENT FIREARM.

WHILE HUNTING THE LAST TWO YEARS THIS RIFLE MISFIRED TWO DIFFERENT TIMES. IN BOTH CASES THE TEMPERATURE WAS ABOUT 30 - 35 DEGREES ABOVE ZERO, THERE WAS A LIGHT RAIN AND I WAS IN A FORESTED AREA.

IN BOTH INSTANCES, AFTER I PULLED THE TRIGGER AND NOTHING HAPPENED. I STARTED TO EJECT THE SHELL AND AS I LIFTED THE BOLT ABOUT 1/2" THE ROUND WENT OFF. I PUT ANOTHER SHELL INTO THE CHAMBER AND IT TOO MISFIRED. I EJECTED IT WITHOUT IT GOING OFF. I THEN PUT A THIRD ROUND INTO THE CHAMBER AND IT FIRED OK. THIS SAME THING HAPPENED ON OCTOBER 30, 1992 AND AGAIN ON OCTOBER 17, 1993. ON OCTOBER 30, 1992 I WAS USING REMINGTON CORE-LOKT 180 GR. BULLETS. ON OCTOBER 17, 1993 I WAS USING 180 GR. BARNES BULLETS THAT I LOADED MYSELF. (IN BOTH INSTANCES I DID MANAGE TO KILL TWO NICE BUCKS)

PLEASE DO WHATEVER NEEDS TO BE DONE TO ELEMIMATE THIS PROBLEM. THANK YOU FOR YOUR ASSISTANCE IN THIS MATTER.

BRAD SHEPHERD	TEL.# 907-772-3555	HOME
P.O. BOX 69	907-772-3000	WORK
PETERSBURG, ALASKA 99833		

SINCERELY,


BRAD SHEPHERD