

APR 1 3 1994

April 5 1994

I purchased a 22-250 model 700 varmint rifle a number of years ago I cannot remember the exact year. I purchased the rifle in Traverse City Michigan. the model No. is 6508205.

On numerous occasions this rifle has fired when I pushed the safety off. I took it to two different Gunsmiths and they both told me they could not tell what causing the problem.

I have not used the gun for years because I am afraid of it misfiring and causing an accident. I was going to trade it in on another Rifle but when I tell them that it fires sometimes when you take the safety off they don,t want it, and I certainly will not sell it to somebody without telling them.

I plan on buying another Remington Rifle this year for my son, I think it will be the Remington Model 700 B.D.L. in the $7 \, \mathsf{mm} \, \mathsf{O8}$ caliber. I would like you to give me the value of my 22 - 250that has the firing problem towards the purchase of this new Model 700. If you would do this I would send you the 22-250 I really don,t want to keep the Rifle at all I just do not trust it.

I also own several other Remington Rifles a model 700 B.D.L. 7mmRem. Mag.a motél 700 B.D.L. 243, two pump shotguns, a nylon 22, and an older 30-06 semi auto. These guns are all of excellent quality and I have been more than satisfied with all of them.

I watched 60 Minutes on Television a few weeks ago and I now realize this is a Manufacturer, s defect.

Thank you and I hope you can resolve this problem.

Sincerely

George J Smith 8560 W. 10 RD. Mesick Mi 49668

Ph. (616) 885-1905

Leone & Smith