

SPORTS WORLD, INC.
5800 South Lewis
TULSA, OKLAHOMA 74105
(918) 742-4027

CUSTOMER WIM 228 TR 76031
 ADDRESS 1613 West Henderson INV. NO. **Y** 21595
 MODEL Rem 700ADL SER. NO. Q 6536225 PHONE McBurney
 PROBLEM: 30-06 OK REC'D. 7-18-94
Safety problem PROMISED
 PARTS AND WORK PERFORMED
 AMOUNT
 RETURN TO FACTORY REM
 PARTS
 LABOR
 TAX
 TOTAL
 SPECIAL INSTRUCTIONS RC01-0228 1241
 RECEIVED BY * Bolt PLETON OF WORK
 Thank you! CASH OK