

Supry, Fred L.

From: Raymond, Joseph J.
Sent: Friday, July 07, 2000 1:03 PM
To: Sanita, Dennis J.; Supry, Fred L.
Subject: JOHN TITTLE RE 10719

I HAVE INSPECTED MR. TITTLES 40XB TARGET RIFLE AND HAVE DETERMINED THAT THE ADJUSTING SCREW FOR THE TRIGGER HAD VIBRATED OUT OF ADJUSTMENT CAUSING THE GUN TO FIRE WHEN THE SAFE WAS RELEASED. I SPOKE TO MR. TITTLE AND TOLD HIM THAT THE PROBLEM HAD BEEN RESOLVED AND THERE SHOULD BE NO FURTHER PROBLEM OF THIS SORT. MR. TITTLE SEEMED A BIT ANNOYED ABOUT THE DAMAGE TO HIS TRUCK SO I TOLD HIM TO SEND IN AN ESTIMATE FOR THE REPAIRS AND REMINGTON WOULD PROBABLY COVER THE EXPENSE. HE SAID HE WOULD AND SEEMED SATISFIED WITH THIS REPLY.

JOE