



RECEIVED

APR 14 1994

CONSUMER SERVICE

Remington Arms Company, Inc.
Wilmington, DE 19898

Recently on a TV program, it featured the lack of federal quality regulations on gun manufactures.

This program pointed out some of the Remington Model 700 BDL, as a UNSAFE gun, since it was subject to mis-fire.

I own a 270 Model 700 BDL, S/N 379853 & have enjoyed it over the years. During this time I have experienced 3 mis-fires with this gun. After chambering a shell & closing the bolt, the gun would fire..NO damage was experienced as a result of these mis-firings, except a few nerves were rattled.

Would you determine if this Model 270, S/N as given was included in a group of gun which might have a problem, resulting in mis-firing.

I had planned to give this gun to my grandson, but under the circumstance, I feel would be unwise, based on the above mention problem.

Please direct your reply to F.A. Tamborello
17826 Asphodel Lane
Spring, Texas 77379

Thanks

F.A. Tamborello
F.A. Tamborello
4-6-94

Mr. & Mrs. Frank A. Tamborello
17826 Asphodel Lane
Spring, TX 77379



Pennington Arms Co. Inc.
Wilmington, DE 19898