

David M. Traw  
680 Danielle Ct.  
Rockwall, Tx 75087  
(972) 722-9942

April 28, 2003

President  
Remington Arms Company, Inc  
Llion, New York 13357-1888

Re: Remington Model 700 .243  
#E6803067

Dear Sir:

On the evening of April 26 while preparing to shoot a wild hog I moved the safety from on to off and the rifle discharged. After unloading the rifle, each time I operate the bolt and move the safety to off the firing pin is released.

When the rifle discharged prematurely I was scared and angry. Now, I'm just angry. I assumed that Remington built safe bolt action rifles. The rifle has not been dropped and the trigger assembly has not been worked on.


I bought this rifle new in 1995 from Williamson Precision Gunsmithing in Hurst, Tx for \$359.00. I would like to return this rifle to Remington for a refund and I am also requesting an additional payment of \$200.00 for loss of pork.

Sincerely,

rem1

PS06201

David Traw  
680 Danielle Court  
Rockwall, Texas 75087



President  
Remington Arms Co, Inc  
Elmer, New York 13357-1888

