

RECEIVING AND ESTIMATING REPORT

COMMENTS

INITIAL JJM	CUSTOMER ORDER NO.						ORDER R 91-04546	
DATE RECEIVED 02/07/91	DATE OPENED 02/15/91	DATE CODE DX 9-73	SERIAL NUMBER 6676256	MODEL AND GRADE 700 30-06 ADL				
ACCESSORIES W/STUDS								

FROM: TOM'S GUN SHOP
203 EAST MADISSON
MEMPHIS MO 63555

SHIP TO: TOM'S GUN SHOP
203 EAST MADISSON
MEMPHIS MO 63555

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	-----------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

"Gun will not fire sometimes & goes off when you close bolt sometimes".

MAIN FAULT: As received, trigger assembly inoperative. Disassembly revealed internal parts of trigger assembly will not move due to contamination by sticky residue. Trigger and connector are sticking to trigger assembly side plates. Rifle has not been properly maintained.

PARTS: After replacement trigger assembly at a normal cost, as gesture of good-will.

REPAIRMAN B.F.	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV 7/90

PS06244