

Dear Mitch,

3/31/85

I have received your letter and M1700 trigger assy., unfortunately, I cannot simply send you a replacement as it is a restricted item.

I noted that both the pound pull screw and the sear engagement screw have been adjusted outside of the factory. Please note that this is not recommended.

Perhaps the simplest solution would be to take your gun to one of our New Gun Repair stations ^{in your area} (list enclosed) with this letter for a N.P.C. replacement. They in turn can attach this letter to their warranty form ^{and return} for reimbursement.

The other option would be to return your gun to my attention for some work as outlined above.

Also; Please find a owners manual enclosed for your convenience