

Repair Order Number



Repair Order Number RE00041773	Description/Serial Number S6353805	Repairman - Bruce Travis Date Received - 2/16/2002
Account # - R-	Model 700 Center Fire Caliber: 375 H&H BDL SS	Estimate Date - Current Date - 2/21/2002
Customer V F GRACE INC 605 EAST 13TH AVE ANCHORAGE. AK 99520 US		Return To V F GRACE INC 605 EAST 13TH AVE ANCHORAGE. AK 99520 US
Phone (H) (907)-272-6431 Phone (W)	Fax (907)-272-7000 Email	

Reported		Problems	Found
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F

Material #	Material Desc	Repair	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
		9/28/99 - Dam				
Total: Could not duplicate TA rusted - appears to have been wet and not cleaned & dried properly. Install new TA, clean action at 1/2 normal charges. FCS 2/22/02						

Condition	REC'D W/ RUST SPOTS ON BOLT PLUG & BBL.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date