Remington Arms Co., Inc.
Product Service
Legal Case #:2932

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete
156159 12/2/2008 12/3/2008 12/3/2008

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact
Reporter A.W. Peterson Gun Shop, Inc A.W. Peterson G 4255 W. Old US 441 Mt. Dora FL 32757 W 352-

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause:4038 Could Not Duplicate Concern
S Fired on bolt closing Concern:1008 Fired on Bolt Closing
Unknown

S Fired on bolt closing Concern: 1008 Fired on

Customer said whe he closed the bolt, the safety was on and he was not touching the trigger, and the gun went off.

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. **DOM** CF/BA 700/3006 SPR 27410 71052875 AW 3/13/2002 4:19:51 AM Remington Original Owner Accessories **Date Purchased** Where Purchased

WAL-MART DC 6003R-REGULAR SCOPE BASE U

CONCERN:FBC

Ammunition Information - None Defined
Other Products Information - None Defined
Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date Cash Date
Settlement APV APV

répair at no charge, goodwill


Repair/Replacement
Cost
65.00
Repair/Replacement
Date
12/3/2008

12/3/2008 returned to AS to install a new TA to restore the customers confidence in the rifle. We could not duplicate the concern fls.

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		12/3/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		AW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

l	Shroud	Slightly Worn; Functioning	
Bolt Extractor	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
		Slightly Worn; Functioning	
	Condition		
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Magazina	Condition	Select	
Magazine	Box Condition	Missing	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/710 SAFETY
Safety	Function	Like new; Functioning	·
	Sub-Assembly	ISS	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	1 ests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	4.5#
	Altered	False	
	Sub-Assembly	Other Remington	·



THE A.W. PETERSON GUN SHOP, INC.

4255 W. Old U.S. 441 MT. DORA, FLORIDA 32757-3299 2932

10. AU 3/02 th

(352) 383-4258 (352) 383-0595 FAX (352) 735-1001

то 	ji Li daj	-14 P		<u> 1900.</u>	<u> </u>	*		<u> </u>	<u></u>	
	-2. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	. #*	11	1.7°	,31	(j	19 mg			

DATE SHIPPED		
LONG TO THE	WARRANTY REPAIR	,4 0
SHIPPED VIA	STANDARD REPAIR	
CUST JOB NO 254	OUR MERCHANDISE	
Giagragia.	CUST. MERCHANDISE	
RA NO	CREDIT RETURN	
[17] 中国的国际中国的国际中国的国际中国的国际中国		

MAKE MAKE	MODEL NO.	SAME CALLEANTS	E NEW YORK WATER	WALLS TO SECUSTOMER	CAST_NAME () ()
		IOSOESCHIPTION		errennen er	
	to the second	Mich Let	a waa ah aa ah a	1011 Bull S	OF PARTICULAR PORTO, P. S. CONTROLLED ST. COM. S. SANDER ST. COM. S. SANDER.
<u> 1319 f 2 f gr. 1 24 19 3</u>					
Bulle She yo				*	
Blower 1	<u> La para da la la</u>	Material Control	to god	Plan Hatte	الميار برقاع كمنطف
14 30 Ch 3					
Johnson Comment	Hickory place	365 CM	policy policy of	<u> </u>	E-Co.
- Lag Gul 5hga 47 - 2)	<u> </u>	3° 13 110 13	I for sure year	Lange	
				`	
·		7	ones in the State of		
			1 Buch		
•					

71052875

Model: 710



Could yot duplicate concein inplace TPA TO RESTOIRE CONRIGER IN 121 fle, chech owen clear. M/C # 230145

Thank You