

Remington Arms Co., Inc.
Product Service
Legal Case #:2110

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
141349	2/7/2008	2/8/2008	2/8/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	D & L Shooting Supplies	D & L		3314 West Shore Road	Warwick	RI	02886		W 401-738-189

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	fires on moving safety	Concern:1007 Fired on Safe Release		Unknown
C				

2/11/08-correspondence from repair-if trigger has any pressure applied to it while the safety is on, when safety is moved to fire gun will fire.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	25859	D6213433	LP	2/21/1995
Date Purchased	Where Purchased	Accessories	Original Owner			
	FABER BROS INC	SOFT CASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA at discount						
	Repair/Replacement Cost	Repair/Replacement Date				

2/11/08-quote sent to replace TA at discount.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/8/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY

Cause	4038	Could Not Duplicate Concern	TRIG ASSM SET SCREWS ALTERED
Barrel	Description		22" 3006 SPR
	Date Code		LP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Magazine	Condition	---Select---	
	Box Condition	Slightly Worn; Functioning	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.015
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	1.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SOFT CASE

Address Information

[illegible]

Repair Search

Refresh

Close

RECEIVED
FEB 11 2008
BY: *[Signature]*

2110

LP 2/95
1.5#
22"
.015

REPAIR
TAG
047633
R326

D & L SHOOTING SUPPLIES, INC.
dba D & L HUNTING & OUTDOOR LODGE
3314 West Shore Road Warwick, RI 02886
(401) 738-1889 (RI) 800-564-1889
Fax (401) 738-9912

CUSTOMER <u>Steven P. Thacker</u>		INVOICE NO. J 047633	
ADDRESS <u>811 Central Pike, Scituate RI</u>		PHONE	DATE RECEIVED
MODEL OR SERIAL NO.		PROMISED	DELIVERED
TROUBLE REPORTED			
DESCRIPTION OF MATERIAL USED		AMOUNT	
<u>if trigger has any pressure applied to it while safety is ON, when safety is moved to fire gun will immediately fire with the movement of the safety.</u>			
TOTAL MATERIALS			
LABOR			
TAX			
TOTAL			
RECEIVED BY		ON COMPLETION OF WORK →	
Thank You! CASH			

21 RI 036-694

D & L INC.
3314 WEST SHORE ROAD
WARWICK, RI 02886

Serial Number: **D6213433**

Model: **700**

RE00141349

could not duplicate concern
Trigger set screws altered
replace TPA, check over,
clean AT 1/2 normal
cost.
Quote